INSTRUMENT PANEL: GAGES CLUSTER
GAGES, SPEEDOMETER

HOT IN RUN BULB TEST OR START

GAGES FUSE
10 AMP
SEE FUSE
BLOCK DETAILS

FUSE
BLOCK

.8 PNK/BLK 39

SEE FUSE
BLOCK DETAILS
CELL 11

S204

.35 PNK/BLK 39

9 C1

OIL
PRESSURE
GAGE

FUEL
GAGE

E

F

VOLTMETER

8 18

FASTEN BELTS
INDICATOR

ILLUMINATION

SPEEDOMETER

SOLID
STATE

INSTRUMENT
CLUSTER
PRINTED
CIRCUIT

TOTAL ODOMETER

TRIP ODOMETER

10 C2

12

2

14 C1

.8 PNK 30

.8 BLK 150

.8 BLK 150

.8 LT GRN/
BLK 537

SEE GROUND
DISTRIBUTION
CELL 14

B C313

S205

PNK 30

VEHICLE
SPEED
SENSOR
CELL 33

FUEL
GAGE
SENDER

FUEL TANK
UNIT
RESISTANCE:
90 OHMS AT FULL
0 OHMS AT EMPTY

F

E

BLK 150

2 BLK 150

A C313

1 BLK 150

SEE GROUND
DISTRIBUTION
CELL 14

G304

G200