

PALO ALTO SPEEDOMETER, INC.

Auto Radio & Instrument Service

718 Emerson Street

PALO ALTO, CALIFORNIA 94301-2410

(650) 323-0243 FAX (650) 323-4632

www.paspeedo.com

info@paspeedo.com

REG. #AD 86482

NAME

Paul

162684

ADDRESS

CITY

DATE

2-3-05

CUST. ORDER NO.

PHONE

943-7071

YEAR & MAKE OF CAR-TYPE OR MODEL

87 Camero

VIN NO.

LICENSE NO.

MILEAGE

WRITTEN BY

DESCRIPTION OF WORK

AMOUNT

AMT. PART NO. NAME OF PART SALE AMT.

NOTE: TO PRESERVE THE WARRANTY ON YOUR REPAIRED SPEEDOMETER/TACHOMETER, YOU MUST REPLACE YOUR CABLE AND HOUSING. WORN CABLE AND HOUSING WILL DAMAGE INSTRUMENT AND VOID THE WARRANTY!

Trip left side loose - plastic holder broken off

Repair mech. speeds - Trip

1 FRAME ASSY NEW

PAID
FEB 08 2005

TOTAL PARTS ▶

UPS

LABOR

90.00

GROUND SERVICE / 3 DAY SELECT / 2nd DAY AIR / NEXT DAY AIR

PARTS

65.00

FED EX #

UPS

INSURE \$

TAX

5.37

AUTHORIZED BY

Paul

TOTAL ▶

160.37

ESTIMATES ARE FOR PARTS AND LABOR

I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH NECESSARY MATERIALS. YOU AND YOUR EMPLOYEES MAY OPERATE ABOVE VEHICLE FOR PURPOSES OF TESTING, INSPECTION OR DELIVERY AT MY RISK. AN EXPRESS MECHANIC'S LION IS ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO. IT IS UNDERSTOOD THAT THE COMPANY ASSUMES NO RESPONSIBILITY FOR LOSS OR DAMAGE BY THEFT OR FIRE TO VEHICLES PLACED WITH THEM FOR STORAGE, SALE, REPAIR OR WHILE ROAD TESTING.