

Edit Log for DFarr_104.bin created by TunerPro.

09/09/2020 20:29:13 Table: AE - CTS Multiplier % changed.
09/09/2020 20:29:49 Table: AE - MAP PW changed.
09/09/2020 20:30:08 Table: AE - TPS PW changed.
09/09/2020 20:30:53 Table: AE - MAP Filter changed.
09/09/2020 20:31:55 Table: AE - RPM Multiplier % changed.
09/09/2020 20:32:47 Table: PE - AFR Commanded changed.
09/09/2020 20:34:23 Scalar: Open Loop - Idle Lean Limit changed from 14.50 AFR
(0x91) to 13.50 AFR (0x87).
09/09/2020 20:35:25 Scalar: PE - AFR Enrich Over Time changed from 1.00 Max
dAFR (0x50) to 1.10 Max dAFR (0x58).
09/09/2020 20:56:08 Table: AE - MAP PW changed.
09/09/2020 20:57:38 Table: AE - TPS PW changed.
09/09/2020 20:58:18 Table: AE - MAP PW changed.