



Fig. 1: Intake Manifold Bolt Tightening Sequence
1988 Pontiac Firebird Trans Am



Snug Tightening Sequence



Final Tightening Sequence

5.0L & 5.7L MFI ENGINES