

Figure 1 - Upper LH Shroud Near "A" Pillar




Figure 3 - LH Side Of Engine Cowl




Figure 5 - Center Of End Panel




Figure 2 - Behind RH Side Of I/P




Figure 4 - Behind Heat-A/C Control Head




Figure 6 - Under I/P, Far LH Side